


# Memo

To: Randy Lyman

From: Bob Corson 


Date: June 29, 2001

Subject: Gasoline in the sewer complaint

At approximately 9:45 am I received your phone call as I was transporting samples from Brenntag Mid-South to the lab at the Southwest Plant. You indicated that the sewer maintenance crew of Omer Boyce and Homer Trantham had observed gasoline in the sewer line they were cleaning. The line is between manholes 63 and 1 on map R16 SW. When I arrived from the lab I checked the three properties served by this sewer line. I arrived at the Pump Handle Convenience Store, 3106 W. Battlefield, at approximately 10:30 am and checked their sample manhole. There was no evidence of gasoline or any odor in the sampling manhole. I then checked the sampling manhole for the Ye Ole Buggy Bath Car Wash, 3146 W. Battlefield. There was no evidence of gasoline or any odor in this sampling manhole. I then contacted the manager of the Mr. Smith's Fast Lube, 3166 W. Battlefield. He was not aware of any gasoline spill or leak from his store. I checked the sewer lift station wet-well for this location and observed no floating oil or rainbow on the water. There was a slight odor of waste oil. There is an oil/water separator on the sewer line directly upstream from the lift station. I then went back to the convenience store and talked to the assistant manager, Carolyn Sutton. She was not aware of any spill or leak at this location. She said that they had their tanks and lines checked in Jan or Feb of this year. Their normal sticking of the tanks has showed not loss of product. She said she would contact her manager about my visit. As I was leaving Boyce and Trantham arrived and Omer when with me to manhole #63 to show me what they had found. When we open the manhole there was no evidence of gasoline, a rainbow or any odor. He said that they would continue to clean lines in the area and if they found any additional gasoline he would call me. See attached map.

At 3:00 pm Ms. Sutton called me at the office and said that they would have their contractor check their lines and tanks in the next day or two. She would call me when she knew when.

3100 W Battlefield



3

MH A1  
1+51E  
T-1252.13  
FL-1247.46

ON L  
MH 45-

2

0+75

1

1

MH B3  
3+46S  
0+00W  
T-1252.53  
FL-1246.67S

3+40

95  
17

42

11

2+80  
8'L

3127

MH B1  
2+04S  
0+00E  
T-1251.15  
FL-1244.42

12

3115

1+46  
9'L

13

3107

1+00  
9'L

10

3033

1+86  
65'L

63

ITPVC

62

RAYNELL ST.

1+35  
65'L

9

3041

3112

MH B2  
1+16W  
T-1251.83  
FL-1246.00

1+10  
8'L

14